

Student Performance Report

Student ID: **1015673**

Name: **Allen, Patricia**

Address: **1127 SE 284th Street
Kirkland, WA 98033**

Date of Birth: / /

Final Grade: **3.11**

Course: **Automotive Technology/AUTO**

Class: **3333**

Curriculum Item(s): All, 145 items reviewed

Date Range: All

Scores Filter: All

Scores Listed: All

Many options are available for this Competency Profile Report. In this example, some of the report parameters selected include: display all scores and dates, average all scores, and display number of recordings.

Score	#	Date	Description	Score	#	Date	Description
3.11			AT - AUTOMOTIVE TECHNOLOGY - NATEF	3		01/30/02	
3.11			AT1 - ENGINE REPAIR	3		02/12/02	
3.09			AT1A - General Engine Diagnosis; Removal and Reinstallation (R & R)	3		04/25/02	
3.5	2		AT1A01 - Interpret and verify complaint; determine needed repairs. P2	2.0	1		AT1A08 - Perform cylinder leakage tests; determine needed repairs. P1
3		03/16/02		2		02/12/02	
4		05/12/02		3.3	3		AT1A09 - Remove engine (front-wheel drive); prepare for tear down. P3
2.6	3		AT1A02 - Inspect engine assembly for fuel, oil, coolant, and other leads; determine needed repairs. P2	3		01/17/02	
2		03/31/02		4		03/01/02	
3		04/12/02		3		05/25/02	
3		04/25/02		3.5	2		AT1A10 - Reinstall engine (front-wheel drive). P3
2.6	3		AT1A03 - Listen to engine noises; determine needed repairs. P2	3		03/01/02	
3		11/12/01		4		05/25/02	
2		01/12/02		3.2	7		AT1A11 - Remove engine (rear-wheel drive); prepare for tear down. P3
3		02/20/02		4		02/12/02	
3.2	9		AT1A04 - Diagnose the cause of excessive oil consumption, unusual engine exhaust color, odor, and sound; determine needed repairs. P2	4		02/28/02	
3		11/02/01		3		03/17/02	
4		12/12/01		3		03/31/02	
3		12/19/01		3		04/12/02	
4		02/11/02		3		05/23/02	
3		02/20/02		3		06/01/02	
3		03/01/02		3.0	6		AT1A12 - Reinstall engine (rear-wheel drive). P3
4		03/12/02		3		02/28/02	
2		04/04/02		4		03/17/02	
3		05/09/02		4		03/31/02	
3.3	8		AT1A05 - Perform engine vacuum tests; determine needed repairs. P3	2		04/12/02	
3		10/29/01		3		05/23/02	
3		11/12/01		2		06/01/02	
4		01/15/02		3.13			AT1B - Cylinder Head and Valve Train Diagnosis and Repair
3		01/15/02		3.0	4		AT1B01 - Remove cylinder head(s); inspect cylinder head(s) for cracks; gasket surface areas for warpage and leakage; check passage condition. P2
4		02/19/02		3		12/01/01	
2		02/28/02		4		01/18/02	
4		03/20/02		3		03/22/02	
4		04/22/02		2		05/25/02	
3.5	7		AT1A06 - Perform cylinder power balance tests; determine needed repairs. P2	3.2	4		AT1B02 - Install cylinder head(s) and gasket(s). P2
3		11/12/01		4		11/12/01	
4		11/12/01		2		12/15/01	
4		01/18/02		4		02/12/02	
4		02/01/02		3		04/12/02	
3		02/12/02					
4		03/10/02					
3		04/20/02					
3.0	5		AT1A07 - Perform cylinder compression tests; determine needed repairs. P2				
2		10/12/01					
4		12/02/01					